

SIEMENS/FURNAS continued
Class 42/16 DP Replacement Parts

49D70035001 Mechanical Interlock for 42AF-42EF
DP Contactors

Part #	Contacts	Contactors	Notes
49ACR0	1NO	42AF-42EF	Side mounted
49ACRC	1NC	42AF-42EF	Side mounted
49ACR6	1NO/1NC	42AF-42EF	Side mounted
49ACR7	2NO	42AF-42EF	Side mounted
49ACR8	2NC	42AF-42EF	Side mounted
49D22125001	1NO	42FE-42GE	Side mounted
49D22125002	1NC	42FE-42GE	Side mounted
49CE42SPDT	SPDT	42FE-42GE	Side mounted
49D54682NO	1NO	42HF-42IF	Side mounted
49D54682NC	1NC	42HF-42IF	Side mounted



49D70035001



49ACR0



49ACRC



49ACR6



49ACR7




49ACR8



49D22125001



49D22125002



49CE42SPDT



49D54682NO



49D54682NC

